











APPENDIX 3: Poznan (Poland) Bottom Ash Processing Photos

POZNAN PLANT (POLAND): BOTTOM ASH TREATMENT AREA

Belt conveyor on the right hand side of the photo, the intermediate storage of approximately five days storage. To the left is the maturation area with movable separation walls.



Bottom ash processing plant within an enclosed building shown below.



Processed bottom ash sorted into different particle sizes. On the far right of the photo are recovered metals.

